

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From:
Sri A.D.D.Samarpana Rau, B.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

To:
The Correspondent,
Oxford International School,
Amaravathi Road,
Guntur District.

Letter No. Soundness Certificate / A8 / GNT / 2023, Dated : 14.03.2024

Sub :- (R&B) Division, Guntur – Structural Soundness Certificates – “Oxford International School, Amaravathi Road, Guntur District - Issue-Regarding.

Ref :- 1)Representation received by Oxford International School, Guntur Dated:- 08.01.2024.

2) Lr No:- Soundness Certificate/SA/2023 Dt:- 11.03.2024 the Deputy Executive Engineer (R&B) Spl Sub Division, Guntur.

* * * * *

With reference to the above, the Deputy Executive Engineer (R&B) Spl Sub-Division, Guntur has personally inspected the ‘Oxford International School’ on 07.03.2024 which was located in Opposite ID Hospital, Amaravathi Road, Guntur District. The existing building is RCC framed structures (G+3) constructed in the year 2021 is utilized for conducting classes.

It is observed that the doors, windows and toilets are in good condition On visual observation, it is observed that the above building is **Structurally sound as on this date.**

Yours faithfully,


Executive Engineer
(R&B) Division, Guntur


14/3/24

1. Copy to the Deputy Executive Engineer (R&B) Spl Sub-Division, Guntur for information.

SOUNDNESS CERTIFICATE

This is to certify that I have inspected OXFORD International School which was located at Opposite ID Hospital, Amaravati road, Guntur on 07.03.2024 and on visual inspection it is observed that the existing building for School is RCC framed structures (G+3) is structurally sound for running the OXFORD International School from 07.03.2024 to 06.03.2025 i.e., one year.

B. Jagadeh Choh
Asst. Executive Engineer
(R&B) Section, Guntur

"caution sign"

J. S. Srinivas
Executive Engineer
(R&B) Division, Guntur

J. S. Srinivas
11/3/24

[Signature]
11-3-24
Deputy Executive Engineer
(R&B) Spl Sub Division, Guntur